

LEGGETT & PLATT PRODUCT INFORMATION SHEET

Product: Bonded Urethane Cushioning

Recommended Use: Carpet and Flooring Underlayment

Contact:

Leggett & Platt Flooring Products Division Office

307 West 7th St.

Suite 1800

Fort Worth, TX 76102

(800) 475-0010

Product Description: Multi-colored solid material formed from bonding various foam products in a urethane media backed with polyethylene film. Product is intended for use as a cushion underlayment for carpet and other flooring surfaces.

Caution: Product is flammable. Keep away from heat, sparks, and flames. Exposure to an ignition source such as open flames, welding operations, smoking materials, exposed lighting, space heaters, electrical sparks, or other heat sources may result in a fire and cause serious personal injury or death.

Storage: Store product in a dry area. Avoid elevated storage temperatures. Keep away from open flames, burning cigarettes, space heaters, exposed light bulbs, exposed wiring, or other ignition sources. Storage areas should be protected by a sprinkler system meeting insurance, NFPA, and/or local codes.

Personal Protective Equipment and First-Aid Measures

Respiratory – Under normal-use conditions including installation and removal, as well as normal usage life as a cushion underlayment, this product should not produce dust requiring the use of a respirator. If grinding, excessively cutting, trimming, or repurposing, a respirator may be required if local or dedicated exhaust does not reduce all exposure levels to below the PEL for respirable dust.

Eyes – Approved safety glasses should be used when handling this product. Dust or other product particulates can cause irritation if it comes in contact with eyes. In the event that dust or particulates in the eye requires first-aid attention, go to eyewash station, open eyelids, and hold them back while flushing with water for at least 15 minutes.

Hands – Approved gloves should be used when conducting manual or mechanical cutting operations.

General Hygiene Considerations: Maintain good housekeeping practices. Do not allow foam scrap or dust to accumulate in the workplace or environment. Pick, sweep, or vacuum up any dust or scrap.

Disposal: Dispose of waste and residues in accordance with applicable federal, state, and local regulations. Recover and recycle, if practical.